## **Inspection Violations List**

Filter: Violation.DateTimeCreated in <Previous month> [12/01/21 - 12/31/21]

AND Inspection.ResultString Not = Approved

Permit # / RFD	Inspection Type / Inspector	Result Brief Violation Description	Date
JADD20-0007	Rough Building	Disapproved Rough Building	04/12/2021
	Building/Elec/Mech Inspector	Provide revised drawing stamped and signed by architecht for LVL repair in new opening a opening for crawl space, New fire place.  No further inspection until revisions are submitted to the village of long grove *PLAN REAPPROVED 9/10/21.	
		At existing crawl space by new opening, please provide repair to bottom plate not bearing	on concrete.
		Also plans show new header at new opening, please provide how that will be mounted and	d secured.
		All exterior outlets shall be sealed.	
		Provide proper hangers where required.	
		At garage anchor bolts at seams missing.	
		exterior tyvex shall have joints sealed.	
		windows shall be properly flashed.	
7040		Rooms shall have fan rated boxes.	
7019			
JADD20-0007	Deck Rough Framing ReInspect	Partially Approv Install latteral load devices as required. Provide bearing for double 2x12 beam at covered porch.	10/11/2021
	Building/Elec/Mech Inspector	Install latteral load devices as required.	
		Provide bearing for double 2x12 beam at covered porch.	
7019		JAMES CRARY	
1019			
JDEK21-0014	Deck Rough Framing ReInspectio	Partially Approv Install hanger at 4 x 4 post. Complete stairs.	11/05/2021
	Building/Elec/Mech Inspector	Install hanger at 4 x 4 post.	
		Complete stairs. Will check these items at final.	
6872		JC	
0072			
JRRF21-0064	Ice and Water	Disapproved Ice and water	12/02/2021
	Building/Elec/Mech Inspector	Contractor suposed to facetime me when ready for inspection.He never did. PS	
1484			
JSWI20-0003	Pool Undergound Gas Piping	Disapproved Pool underground gas piping	12/02/2021
	Plumbing Inspector	Not ready.PS	
3111	- •		
JSWI20-0003	Pool Underground Diumbing	Disapproved Pool underground plumbing	12/02/2021
JOVVIZU-UUU3	Pool Underground Plumbing Plumbing Inspector	Not ready.PS	
3111	i lumbing mapeoloi	•	

	Code Enforcement Work w/o Perm	Not Complied Working without a permit	12/03/2021
	Building/Elec/Mech Inspector	Shed materials still on site, no change from previous inspection.  JC	
3434			
	Conservancy Dist Encroachment	Violation(s) Initial property complaint	12/07/202
	Building/Elec/Mech Inspector	I visited the site and it appears trees were removed compared to google earth picture. I to sent them to Margarita at Long Grove.	ok pictures and
		Thanks,	
1754		Joel	
HAR21-0023	Final Patio, Walk, Stoop	Disapproved Final Patio, walk, stoop	12/07/202
	Building/Elec/Mech Inspector	Front walk step shall not exceed 3/8 variance.	
		Please submit for an electrical permit for all new electrical around patio.*	
		Okay to final patio only. Thanks, Joel	
5724		*12/21/21 RECD PERMIT APPLICATION AND PLANS FOR ELECTRICAL.	
JELE21-0005	Final Electrical	Disapproved Final Electrical	12/08/202
	Building/Elec/Mech Inspector	Remove old electrical meter at side of house.	
		Drywall needs to be completed.	
		Please call to reschedule once items have been completed. Thanks, Joel	
7033			
JNSF21-0005	Footing PrePour	Disapproved Footing pre pour	12/08/2021
	Building/Elec/Mech Inspector	Not ready at this time. Please call to reschedule	
		Thanks,	
4553		Joel	
ISID21-0003	Final Siding	Disapproved Final Siding	12/08/202
	Building/Elec/Mech Inspector	No one was home. Please have plans on site.	
		Please reschedule.	
		Thanks, Joel	
2505		30 <del>0</del> 1	
	Code Enforcement Work w/o Perm	No Violation property complaint	12/09/2021
	Building/Elec/Mech Inspector	I beleive the correct address should be 2373 checker. There should be an open complain	t for it.
2371			

JCAL21-0005	Business CO Plumbing ReInspect	Disapproved Business CO Plumbing Re-Inspect	12/13/2021
OCO21-0005	Plumbing Inspector	No Hot Water at Front hand sink and leaking badly.	
		3 RPZ's all approved. Water tempature Approved. Splash Guards in place.	
3976		Will call for reinspection when front hand sink is fixed	
JADD20-0007	Final Electrical	Disapproved Final Electrical	12/14/2021
	Building/Elec/Mech Inspector	Install two missing receptacles at kitchen.	
		All new receptacles are to be tamper resistant.	
		All exterior receptacles are to be WR tamper resistant GGFCI protected.	
		Properly fill opening at electrical panel in garage at 100 amp breaker.	
		Master bath tub to be GFCI portected.	
		All receptacles in crawl to be GFCI protected and tamper resistant.	
7019			
JADD20-0007	Final Building	Disapproved Final Building	12/14/2021
	Building/Elec/Mech Inspector	Cpver paper face of insulation at master bath tub.	
		Add smoke detectors as required at all existing bedrooms and with in 15 feet of all bedrooms	S.
		Install required CO detectro within 15 feet of all bedrooms.	
		Cover paper face or remove at insulatoin in crawl at box joist.	
		Provide 3 X 3 landing at exterior side of front stoop per appproved plans and as required.	
7040		All riser heights at the garage stairs and stairs at front door to be no more than 7-3/4 inches than 3/8 inch difference between.	with no more
7019			
JDEM21-0004	Final Demolition	Disapproved Final Demo	12/14/2021
	Building/Elec/Mech Inspector	No one on site for inspection.	
		Two windows at first floor boarded up to be repaired.	
		Repair boarded up door east wall frist floor.	
		Remove all construction debris from east side of prpperty.	
407		JC	
JRRF21-0025	Ice & Water	Disapproved Ice and water shield	12/15/2021
	Building/Elec/Mech Inspector	Ice and water shield covered prior to arrival on site.	
3137		JC	
	Property Maintenance	Violation(s) Property Maintenance	12/16/2021
	Building/Elec/Mech Inspector	Not Able To Enter Property	
5175			

JRRF21-0025	Ice & Water-PHOTOS	Partially Approv	12/16/2021
	Building/Elec/Mech Inspector	Submited photos for ice and water shield are approved.  JC	
3137			
JNSF21-0001	Electrical Service	Disapproved Electrical service	12/16/2021
	Building/Elec/Mech Inspector	Breaker undersized	
4270			
	Tree Removal	Violation(s) Tree removal	12/17/2021
	Building/Elec/Mech Inspector	Owner stated two trees were removed and several others were trimed. He will apply for tree reduced JC	emoval permit.
1564		JC	
JSWI20-0003	Pool Deck PrePour	Disapproved Pre pour	12/20/2021
	Building/Elec/Mech Inspector	I went to the property and the gates were locked. Please call to reschedule.	
		Joel	
3111			
JADD20-0010	Site Complaint - Conservancy	Partially Approv Stored materials	12/22/2021
	Building/Elec/Mech Inspector	Project is using Park District property to stage materials for project at 3819 Nottingham. Encre east property to west of walking path. Has dammaged grass. Contractor to removed all mater for 12-23-21 to check status.  JC	
3819			
JADD20-0010	Post Stop Work Order	Partially Approv	12/23/2021
	Building/Elec/Mech Inspector	All materials have been removed. Area needs to be restored. Stop work notice has been post JC	ed on house.
3819			
JNSF21-0005	Foundation Backfill	Disapproved Back fill	12/27/2021
	Building/Elec/Mech Inspector	At rear of house the footing does not have the proper angle of repose and also at one area it the dirt has colapsed and increased the overhang of step wall. please provide a letter from an conditions of footing are okay or provide the corrections. The letter shall be stamped and sign architect.	chitect stating
		Thanks, Joel	
4553			
JINT21-0019	Rough Electrical	Disapproved Rough electrical	12/27/2021
	Building/Elec/Mech Inspector	Not ready at this time. This was more of informational.  Please schedule once ready for inspection.	
		thanks, Joel	
6740		0061	

JNSF16-0007	FCO Building Reinpsect  Building/Elec/Mech Inspector	Disapproved  Re final FEM  Guards at garage need to hold 200 lbs. Table R301.5  Guards at garage need handrail to return. R311.7.8.2  Garage door needs to be self closing; add more tension to spring.R302.5.1  At this time there is no sidewalk from main entrence to driveway. R311.1 and per approved pla  The pool remains in non working conditions at this time.	12/28/2021 ns.
		Handrail at exterior to basement shall be min 34" max 38" and shall be returned.R311.7.8.1  2 fireplaces are not completed at this time.  Complete radon caulk around all ejector pits.	
6521		Please reschedule inspection once items have been completed. Thanks, Joel	
JRRF21-0100 3813	Ice & Water  Building/Elec/Mech Inspector	Partially Approv Ice & Water Front of Garage and rear of Garage Ice & Water in place	12/30/2021
	Code Enforcement Work w/o Perm Building/Elec/Mech Inspector	Violation(s)  Work with out permit  I stopped at the property and did see the trailers but there was no one there. I took pictures and to Margerita. We will do a follow up in 2 weeks.  Thanks, Joel	12/30/2021 d sent them
1889		1/4/22 PETE SCHUBKEGEL DETERMINED THAT THE TRAILERS ARE ON A PROPERTY T BELONGS TO THE COUNTY (ADDRESS 18163). 1889 IS NOT THE CORRECT ADDRESS.	HAT
JDEK21-0016 6903	Final Deck  Building/Elec/Mech Inspector	Disapproved Final Deck Fill in all nail holes at hurricane clips. All un-used material need to be removed from site. Please call to reschedule inspection. Thanks, Joel	12/30/2021

Total: 31